



Certified Appraisal

Car:

VIN:

Owner:

Summary of Appraisal:

This is a partially restored car in "Rat Rod" condition (meaning parts were pulled from all makes of vehicles). It is non-operable and needs extensive attention and a total restoration.

A #1 totally restored value is \$26,900

Appraised Value:

John "Hago" Chuchian
Hagos Classic Cars, Owner

Date

Appraisal Summary – Details are on the following pages

Appraisal Detail

Vehicle Information:

Year:

1950

Make:

Ford

Model:

VIN#:

HOMP127805

Odometer:

Exterior:

Paint and Color Condition:

Unfinished paint and primer.

Size and Number of Dents, Dings, and Scratches:

Multiple dents, dings and scratches all over the vehicle.

Rust Location and Amount:

Rust bubbles on most of the lower body.

Tire Size, Brand and Tread wear:

60 Rear, 70 Front – BF Goodrich. Tires have good tread. Age unknown.

Wheel Type and Make:

Cragar wheels. Good condition.

If Convertible, condition of soft top and/or hard top:

Hard Top, good condition.

Other:

Body kind of rough.



Appraisal Detail

Interior:

Radio/Stereo – Make, type and condition:

Non working

Dashboard (including gauges) condition:

Old, mis-matched

Interior Door Panels (including locks and window cranks):

None

Seat Condition and Quality:


Old, mis-matched

Headliner:

None.

Other:

Interior is pretty much non-existent.



Appraisal Detail

Mechanical:

Motor Size and condition:

Unknown, BIG BLOCK Ford. Appears old, dusty, not started in years.

Transmission type and condition:

Unknown automatic.

Suspension Condition:

Front suspension and rear have been upgraded, however rusty and dusty from long period of sitting.

Shocks and Brakes:

Old, non-working

Air Conditioning and Heater condition:

None

Other:



Appraisal Detail



Appraisal Detail



Appraisal Detail

